

CLOUD HILL & BREEDON
Quarries Report
September 2026

Quarry Development:

The quarry continues to produce stone from the faces on the south and western side of the quarry in accordance to the quarry development plan

Blasting:

Cloud Hill Quarry

During all blasting operations, monitoring has taken place at either Worthington Village or Mill Farm.

We have received no complaints regarding blasting at Cloud Hill

Breedon Quarry:

Production

We continue to produce the material at Breedon using the Rock Hawg surface miner
With no issues

Road Condition:

The company continues to operate a sweeper between both sites and all goods vehicle are required to pass through one of the two wheel wash units at Cloud Hill before exiting the quarry

Dust:

We have a series of sprinkler systems in place and a water bowser to ensure airborne dust is kept to a minimum.

In the summer due to the extreme heat and dry conditions we hired in a portable fogging machine too try to keep the air bourn dust to a minimum

Noise:

We have a independent company to complete a noise survey as per our planning permission and the quarry has been compliant every visit

We have received no complaints since the last meeting regarding noise

Neil Gamble
Quarry Manager